LEW CORPORATION
The Environmental Company℠

1090 Bristol Road
Mountainside, NJ 07092
(908) 654-8068
(800) 783-0567
Fax 908-654-8069

LEAD IN DRINKING WATER REPORT

Performed At:
Hunterdon Central Regional High School
84 Route 31 Flemington, NJ 08822

Performed For:
Hunterdon Central Regional High School
Don Thornton
84 Route 31
Flemington, NJ 08822

Prepared By:
LEW Corporation
1090 Bristol Road
Mountainside, NJ 07092

Phone (908) 654-8068
Fax (908) 654-8069
Website http://www.LEWCorp.com

Inspection Date: 4/30/2017
Project Number: 170330

Table of Contents

Contact Information 3
Introduction 4
Sampling Methodology 4
Drinking Water Results 5
Recommendations 5
Additional Recommendations 5

Appendices

Appendix A Exceedances
Appendix B Recommendations
Appendix C All results
Appendix D Floor Plan(S)
Appendix E Laboratory Data

Contact Information

Agency

Client Contact:	Don Thornton
Client Name:	Hunterdon Central Regional High School
Street Address	84 Route 31 Flemington, NJ 08822
Phone Number:	(908) 284-7172

Risk Assessor(s)

Site Assessor(s):	Alex Salvador
License:	NJDOH #022779
Signature:	
Date:	May 16, 2017
E-Mail	asalvador@lewcorp.com

Firm

Organization:	LEW Corporation
Certification #:	NJDCA 00015 E
Street:	1090 Bristol Road
City, State & Zip:	Mountainside, New Jersey 07092
Phone Number:	908-654-8068
Web Address:	http://www.lewcorp.com

Laboratory

Organization:	Environmental Hazard Services, LLC
Street:	7469 Whitepine Road
City, State & Zip:	Richmond, VA 23237
NJDEP Certification #	VA008
Phone Number:	800-347-4010

Introduction

LEW Corporation was contracted by Hunterdon Central Regional High School to test for the presence of lead in drinking water in one school in the district.

Sampling Methodology

LEW Corporation followed the July 13, 2016 amendments to NJAC 6A:26. Full details on sampling practices can be found in Districts Sampling Plan.

All samples were collected in 250mL wide mouth plastic containers that was prepackaged by the analytical laboratory. The sample containers may contain nitric acid, if expedited analysis is required. If not, nitric acid will be added to each sample upon arrival at the laboratory. At each sample location, the first draw sample was taken after it was determined that the water had been standing in the plumbing system for greater than eight hours but less than forty-eight hours. If second draw samples were collected, they were collecting following a flushing protocol outlined in the District's Sampling Plan.

Drinking Water Results

On April 30, 2017, LEW Corporation collected the following number of water samples:

Hunterdon Central Regional High School- Upper Campus

- 44 first draw samples collected and 1 quality control sample
- 1 sample above the 15ppb action level

Hunterdon Central Regional High School- Lower Campus

- 59 first draw samples collected
- 1 sample above the 15ppb action level

The complete list of samples that exceeded the 15ppb limit can be found in Appendix A. The complete list of all sample results can be found in Appendix C. The laboratory results can be found in Appendix E.

Certain outlets could not or were not tested due to various reasons. The following table lists those locations and the reason why samples were not collected.

School	Sample Location	Reason for not testing.
Upper Campus	HALL NEAR 137	Sample Not Received by Laboratory

Recommendations

Those outlets where the first draw sample tested below 15ppb are not considered to be elevated and no mitigation is necessary.

For those outlets where the first draw sample exceeds 15ppb the following steps are recommended:

1) Immediately discontinue use of the outlets.
2) Conduct second draw (flush) samples on these outlets to further delineate source of contamination.

A complete list of recommendations per outlet can be found in Appendix B.

Additional Recommendations

1) Follow-up samples should be collected after any remediation efforts in order to determine the efficacy of the work.
2) Any of the inoperable/non-functioning outlets listed above that are brought back into service should be sample.
3) Comply with all requirements set forth in NJAC 6A:26.

Appendix A Exceedances

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
1st Draw Samples					
Hunterdon Central Regional High School					
Upper Campus					
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS19	ROOM 104	17.8
Lower Campus					
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS33	11/12 KITCHEN B	26.6

Appendix B Recommendations

Building	Sample ID	Sample Description	Remediation Recommendation
Hunterdon Central Regional High School			
Upper Campus			
Hunterdon Central Regional High School	HCRHSUCS19	ROOM 104	Immediately discontinue use of the outlets. Conduct second draw (flush) samples on these outlets to further delineate source of contamination.
Lower Campus			
Hunterdon Central Regional High School	HCRHSLCS33	11/12 KITCHEN B	Immediately discontinue use of the outlets. Conduct second draw (flush) samples on these outlets to further delineate source of contamination.

Appendix C All Results

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Hunterdon Central Regional High School					
Upper Campus					
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF1	HALL NEAR 200	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS2	ROOM 207 A	4.14
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS3	ROOM 207 B	2.82
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS4	ADMIN BREAK ROOM	1.59
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF5	HALL NEAR 206	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF6	HALL NEAR 9/10 HOUSE OFFICE	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS7	9/10 HOUSE OFFICE BREAK RM	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF8	HALL LOBBY LOW	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF9	HALL LOBBY HIGH	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF10	HALL NEAR 304	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF11	HALL NEAR 116	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS12	ROOM 115	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF13	HALL NEAR 106	1.50
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS14	ROOM 103 A	3.02
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS15	ROOM 103 B	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS16	ROOM 103 C	1.36
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS17	ROOM 103 D	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS18	ROOM 103 E	1.17

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Hunterdon Central Regional High School					
Upper Campus					
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS19	ROOM 104	17.8
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF20	HALL NEAR PLANETARIUM	<1.00
Hunterdon Central Regional High School	04/30/2017	05/10/2017	HCRHSUCF21	HALL NEAR 100 BASEMENT	2.38
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS22	TRAINER RM COOLER FILL STATION	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCIM23	TRAINER ROOM B	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF24	HALL NEAR 157 GYM HIGH	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF25	HALL NEAR 157 GYM LOW	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF26	GIRLS LOCKER GYM A HIGH	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF28	BOYS LOCKER GYM B LOW	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF29	BOYS LOCKER GYM A HIGH	1.59
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF30	CAFE 172	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF31	9/10 KITCHEN A	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCIM32	9/10 KITCHEN B	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS33	9/10 KITCHEN C	1.96
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS34	9/10 KITCHEN D	5.64
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS35	9/10 KITCHEN E	2.73
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS36	9/10 KITCHEN F	1.59
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS37	9/10 KITCHEN G	6.60
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCH38	9/10 KITCHEN H	4.72
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS39	9/10 KITCHEN I	3.36
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF40	CAFE 174 F	1.04

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Hunterdon Central Regional High School					
Upper Campus					
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF41	CAFE 173 A	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS42	CAFE 173 E	2.21
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF43	HALL NEAR 128	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF44	HALL NEAR 137	*
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCF45	HALL NEAR 150	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS46	KITCHEN J	3.30
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSUCS47	SUNROOM	<1.00

*SAMPLE NOT RECEIVED BY THE TESTING LABORTORY.

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Hunterdon Central Regional High School					
Lower Campus					
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF1	HALL NEAR 406 G	<1.00
Upper Campus	04/30/2017	05/09/2017	HCRHSLCF2	HALL NEAR 406 B	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS3	WORK ROOM	7.07
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF4	ROOM 500	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF5	HALL NEAR 504 DOOR	3.11
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF6	HALL NEAR 504	1.10
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF7	HALL NEAR 518 LOW	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF8	HALL NEAR 518 HIGH	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF9	HALL NEAR 612	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF10	HALL NEAR 646	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS11	ROOM 650	1.27

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Hunterdon Central Regional High School					
Lower Campus					
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF12	HALL NEAR 652	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF13	ROOM 657	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS14	ROOM 657	1.43
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF15	HALL NEAR SS OFFICE	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCIM16	ROOM 702 B	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF17	ROOM 702 C	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS18	ROOM 714	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS19	ROOM 716 A	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS20	ROOM 716 B	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS21	ROOM 716 C	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS22	ROOM 716 D	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS23	ROOM 716 E	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS24	ROOM 716 F	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF25	HALL NEAR 810 LOW	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF26	HALL NEAR 810 HIGH	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF27	HALL NEAR 821 LOW	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF28	HALL NEAR 821 HIGH	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS29	ROOM 825	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF30	COMMONS KITCHEN SIDE LOW	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF31	COMMONS KITCHEN SIDE	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS32	11/12 KITCHEN A	1.94
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS33	11/12 KITCHEN B	26.6

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Hunterdon Central Regional High School					
Lower Campus					
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS34	11/12 KITCHEN C	1.77
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS35	11/12 KITCHEN D	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS36	11/12 KITCHEN E	4.51
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS37	11/12 KITCHEN F	11.9
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCH38	11/12 KITCHEN G	2.66
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS39	11/12 KITCHEN H	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCIM40	11/12 KITCHEN I	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF41	COMMONS NEAR SCHOOL STORE	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF42	COMMONS NEAR SCHOOL STORE HIGH	1.19
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF43	FIELD HOUSE G LOCKER A	3.79
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF44	FIELD HOUSE G SIDE FOYER	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF45	WRESTLING ROOM	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF46	FIELD HOUSE B SIDE FOYER	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF47	FIELD HOUSE B LOCKER A	1.74
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF48	ROOM 900 PREP	3.08
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF49	ROOM 904 PREP	5.02
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF50	HALL NEAR 910 LOW	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF51	HALL NEAR 910 HIGH	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS52	ROOM 914 PREP	4.12
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF53	HALL NEAR 919 LOW	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF54	HALL NEAR 919 HIGH	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS55	ROOM 923 PREP	<1.00

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Hunterdon Central Regional High School					
Lower Campus					
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS56	11/12 KITCHEN J	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCS57	11/12 KITCHEN K	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF58	11/12 LEFT COMMONS	<1.00
Hunterdon Central Regional High School	04/30/2017	05/09/2017	HCRHSLCF59	11/12 RIGHT COMMONS	<1.00

Appendix D Floor Plan(s)

Hunterdon Central Regional High School
84 Route 31, Flemington, NJ 08822

Building Constructed 1955/58/62/96/98/2007
Three Story
215,503 SF
72 Acres
B 27 L 3

40° 30' 57.96" N 74° 51' 08.60" W @49m
Google Earth Pro



Hunterdon Central Regional High School
84 Route 31, Flemington, NJ 08822

Building Constructed Music/Communication
1971/92/2007
Single Story
IMC 21,799 SF
CON 19,431 SF
72 Acres
B 27 L 3

40° 31' 04.62" N 74° 51' 01.57" W @42m
Google Earth Pro

WV-SF346
WV-SW395
WV-SC385
WV-SW559
WV-SC386



WV-SF346
WV-SW395
WV-SC385
WV-SW559
WV-SC386

LC14
LC13
LC15
LC16
LC8
LC12
LC11
LC9
LC6
LC7
LC10
LC17
LC18
LC21
LC19
LC20
LC22
LC23
LC24
LC25
LC26
LC27
LA33
LD28
LA29
LA30
LA1
LA2
LA3
LA4
LB5
LD22
LD23
A1
A2
A3
A4

Hunterdon Central Regional HS
84 Route 31, Flemington, NJ 08822

Building Constructed 1971/98/2007
Two Story
218,096 SF
72 Acres
B27 L3
40° 31' 13.57"N 74° 51' 00.83" W @43m
Google Earth Pro

Appendix E Laboratory Data

Environmental Hazards Services, LLC

7469 Whitepine Rd.● Richmond, VA 23237 ● 800-347-4010•jdickerson@leadlab.com

May 10, 2017

LEW Corp
1090 Bristol Rd.
Mountainside, NJ 07092

PROJECT INFORMATION

Project/Test Address:	170330; 84 State Route 31; Flemington, NJ 08822
Report Number:	17-05-00447
Analysis Type:	Lead – Standard Method 3113B
Lab Accreditation Number:	NJ-VA008/NY-11714
Results, Discussion Qualifiers:	N/A

Julie Dickerson
Laboratory Administrator
Environmental Hazards Services, LLC

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 17-05-00447

Client: LEW Corp
1090 Bristol Rd
Mountainside, NJ 07092

Received Date: 05/03/2017
Reported Date: 05/10/2017
Sampled By: Alex Salvador
Tech Certification #: LA 9374

Project/Test Address: 170330; 84 State Route 31; Flemington, NJ 08822

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
17-05-00447-001	HCRHSLC F1	04/30/2017	HALL NEAR 406 G	<1.00	05/05/2017	
17-05-00447-002	HCRHSLC F2	04/30/2017	HALL NEAR 406 B	<1.00	05/05/2017	
17-05-00447-003	HCRHSLC S3	04/30/2017	WORK ROOM	7.07	05/05/2017	
17-05-00447-004	HCRHSLC F4	04/30/2017	ROOM 500	<1.00	05/05/2017	
17-05-00447-005	HCRHSLC F5	04/30/2017	HALL NEAR 504 DOOR	3.11	05/05/2017	
17-05-00447-006	HCRHSLC F6	04/30/2017	HALL NEAR 504	1.10	05/05/2017	
17-05-00447-007	HCRHSLC F7	04/30/2017	HALL NEAR 518 LOW	<1.00	05/05/2017	
17-05-00447-008	HCRHSLC F8	04/30/2017	HALL NEAR 518 HIGH	<1.00	05/05/2017	
17-05-00447-009	HCRHSLC F9	04/30/2017	HALL NEAR 612	<1.00	05/05/2017	
17-05-00447-010	HCRHSLC F10	04/30/2017	HALL NEAR 646	<1.00	05/05/2017	
17-05-00447-011	HCRHSLC S11	04/30/2017	ROOM 650	1.27	05/05/2017	
17-05-00447-012	HCRHSLC F12	04/30/2017	HALL NEAR 652	<1.00	05/05/2017	
17-05-00447-013	HCRHSLC F13	04/30/2017	ROOM 657	<1.00	05/05/2017	

Environmental Hazards Services, LLC

7469 Whitepine Rd.● Richmond, VA 23237 ● 800-347-4010•jdickerson@leadlab.com

May 10, 2017

LEW Corp
1090 Bristol Rd.
Mountainside, NJ 07092

PROJECT INFORMATION

Project/Test Address:	170330; 84 State Route 31; Flemington, NJ 08822
Report Number:	17-05-00453
Analysis Type:	Lead – Standard Method 3113B
Lab Accreditation Number:	NJ-VA008/NY-11714
Results, Discussion Qualifiers:	Client sample number HCRHSUCF27 was voided by client. Client sample number HCRHSUCF44 was not received.

Julie Dickerson
Laboratory Administrator
Environmental Hazards Services, LLC

Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 17-05-00453

Client: LEW Corp
1090 Bristol Rd
Mountainside, NJ 07092

Received Date: 05/03/2017
Reported Date: 05/10/2017
Sampled By: Alex Salvador
Tech Certification #: LA 9374

Project/Test Address: 170330; 84 State Route 31; Flemington, NJ 08822

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
17-05-00453-001	HCRHSUCF1	04/30/2017	HALL NEAR 200	<1.00	05/09/2017	
17-05-00453-002	HCRHSUCS2	04/30/2017	ROOM 207 A	4.14	05/09/2017	
17-05-00453-003	HCRHSUCS3	04/30/2017	ROOM 207 B	2.82	05/09/2017	
17-05-00453-004	HCRHSUCS4	04/30/2017	ADMIN BREAK ROOM	1.59	05/09/2017	
17-05-00453-005	HCRHSUCF5	04/30/2017	HALL NEAR 206	<1.00	05/09/2017	
17-05-00453-006	HCRHSUCF6	04/30/2017	HALL NEAR 9/10 HOUSE OFFICE	<1.00	05/09/2017	
17-05-00453-007	HCRHSUCS7	04/30/2017	9/10 HOUSE OFFICE BREAK RM	<1.00	05/09/2017	
17-05-00453-008	HCRHSUCF8	04/30/2017	HALL LOBBY LOW	<1.00	05/09/2017	
17-05-00453-009	HCRHSUCF9	04/30/2017	HALL LOBBY HIGH	<1.00	05/09/2017	
17-05-00453-010	HCRHSUCF10	04/30/2017	HALL NEAR 304	<1.00	05/09/2017	
17-05-00453-011	HCRHSUCF11	04/30/2017	HALL NEAR 116	<1.00	05/09/2017	
17-05-00453-012	HCRHSUCS12	04/30/2017	ROOM 115	<1.00	05/09/2017	
17-05-00453-013	HCRHSUCF13	04/30/2017	HALL NEAR 106	1.50	05/09/2017	

Environmental Hazards Services, L.L.C

Client Number: 201327 **Report Number:** 17-05-00453

Project/Test Address: 170330; 84 State Route 31; Flemington, NJ 08822

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
17-05-00453-014	HCRHSUCS14	04/30/2017	ROOM 103 A	3.02	05/09/2017	
17-05-00453-015	HCRHSUCS15	04/30/2017	ROOM 103 B	<1.00	05/09/2017	
17-05-00453-016	HCRHSUCS16	04/30/2017	ROOM 103 C	1.36	05/09/2017	
17-05-00453-017	HCRHSUCS17	04/30/2017	ROOM 103 D	<1.00	05/09/2017	
17-05-00453-018	HCRHSUCS18	04/30/2017	ROOM 103 E	1.17	05/09/2017	
17-05-00453-019	HCRHSUCS19	04/30/2017	ROOM 104	17.8	05/09/2017	
17-05-00453-020	HCRHSUCF20	04/30/2017	HALL NEAR PLANETARIUM	<1.00	05/09/2017	
17-05-00453-021	HCRHSUCF21	04/30/2017	HALL NEAR 100 BASEMENT	2.38	05/10/2017	
17-05-00453-022	HCRHSUCS22	04/30/2017	TRAINER RM COOLER FILL STATION	<1.00	05/09/2017	
17-05-00453-023	HCRHSUCIM23	04/30/2017	TRAINER ROOM B	<1.00	05/09/2017	
17-05-00453-024	HCRHSUCF24	04/30/2017	HALL NEAR 157 GYM HIGH	<1.00	05/09/2017	
17-05-00453-025	HCRHSUCF25	04/30/2017	HALL NEAR 157 GYM LOW	<1.00	05/09/2017	
17-05-00453-026	HCRHSUCF26	04/30/2017	GIRLS LOCKER GYM A HIGH	<1.00	05/09/2017	
17-05-00453-027	HCRHSUCF28	04/30/2017	BOYS LOCKER GYM B LOW	<1.00	05/09/2017	
17-05-00453-028	HCRHSUCF29	04/30/2017	BOYS LOCKER GYM A HIGH	1.59	05/09/2017	
17-05-00453-029	HCRHSUCF30	04/30/2017	CAFE 172	<1.00	05/09/2017	
17-05-00453-030	HCRHSUCF31	04/30/2017	9/10 KITCHEN A	<1.00	05/09/2017	
17-05-00453-031	HCRHSUCIM32	04/30/2017	9/10 KITCHEN B	<1.00	05/09/2017	
17-05-00453-032	HCRHSUCS33	04/30/2017	9/10 KITCHEN C	1.96	05/09/2017	
17-05-00453-033	HCRHSUCS34	04/30/2017	9/10 KITCHEN D	5.64	05/09/2017	

Environmental Hazards Services, L.L.C

Client Number: 201327 **Report Number:** 17-05-00453

Project/Test Address: 170330; 84 State Route 31; Flemington, NJ 08822

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
17-05-00453-034	HCRHSUCS35	04/30/2017	9/10 KITCHEN E	2.73	05/09/2017	
17-05-00453-035	HCRHSUCS36	04/30/2017	9/10 KITCHEN F	1.59	05/09/2017	
17-05-00453-036	HCRHSUCS37	04/30/2017	9/10 KITCHEN G	6.60	05/09/2017	
17-05-00453-037	HCRHSUCH38	04/30/2017	9/10 KITCHEN H	4.72	05/09/2017	
17-05-00453-038	HCRHSUCS39	04/30/2017	9/10 KITCHEN I	3.36	05/09/2017	
17-05-00453-039	HCRHSUCF40	04/30/2017	CAFE 174 F	1.04	05/09/2017	
17-05-00453-040	HCRHSUCF41	04/30/2017	CAFE 173 A	<1.00	05/09/2017	
17-05-00453-041	HCRHSUCS42	04/30/2017	CAFE 173 E	2.21	05/09/2017	
17-05-00453-042	HCRHSUCF43	04/30/2017	HALL NEAR 128	<1.00	05/09/2017	
17-05-00453-043	HCRHSUCF45	04/30/2017	HALL NEAR 150	<1.00	05/09/2017	
17-05-00453-044	HCRHSUCS46	04/30/2017	KITCHEN J	3.30	05/09/2017	
17-05-00453-045	HCRHSUCS47	04/30/2017	SUNROOM	<1.00	05/09/2017	

Method: SM 3113B-2010

Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

17-05-00453

Due Date:
05/10/2017
(Wednesday)
AE

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

SN

Project Name / Collection Address: 10330, 84 State Route 31 City/State/Zip: Flemington NJ 08822
(Required)

P.O. #: ---------- Sampled By: Alex Salvador License # (If Required): ----------

Water Source: (Required) (Check One) Public [X] Well [ ] Well Tag # (If Applicable): _____

[X] 5 Day Turnaround	[ ] 3 Day Turnaround	[ ] 2 Day Turnaround	[ ] 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
1	HCRHS UC F1	Hall near 200	4/30/17	7:30 AM / PM	X					
2	S2	Room 207 A		AM / PM						
3	S3	Room 207 B		AM / PM						
4	S4	Admin Break Room		AM / PM						
5	F5	Hall near 206		AM / PM						
6	F6	Hall near 9/10 House office		AM / PM						
7	S7	9/10 House office Break Rm		AM / PM						
8	F8	Hall Lobby Low		AM / PM						
9	F9	Hall Lobby High		AM / PM						
10	F10	Hall Near 304		AM / PM						

Released by:	Alex Salvador	Signature:	Date/Time: 4/30/17
Released by:		Signature:	Date/Time:

5/3/17

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

453
~ For Lab Use Only ~

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address (Required): 170330, 84 State Route 31 City/State/Zip (Required): Clinton NJ 08822

P.O. #: ---------- Sampled By: Alex Salvador License # (If Required): ----------

Water Source (Required): (Check One) Public [X] Well [ ] Well Tag # (If Applicable): _____

[X] 5 Day Turnaround [ ] 3 Day Turnaround [ ] 2 Day Turnaround [ ] 1 Day Turnaround - Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
11	HCRHS UCF11	Hall near 116	4/30/17	7:45 AM/PM	X					
12	S12	Room 115		AM/PM						
13	F13	Hall near 106		AM/PM						
14	S14	Room 103 A		AM/PM						
15	S15	Room 103 B		AM/PM						
16	S16	Room 103 C		AM/PM						
17	S17	Room 103 D		AM/PM						
18	S18	Room 103 E		AM/PM						
19	S19	Room 104		AM/PM						
20	F20	Hall near planetarium		AM/PM						

Released by: Alex Salvador Signature: [signature] Date/Time: 4/30/17

Released by: Signature: Date/Time:

[signature] 5/3/17

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

453
~ For Lab Use Only ~

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: 170330/ 84 State Route 31 City/State/Zip: Flemington NJ 08822
(Required)

P.O. #: ---------- Sampled By: Alex Salvador License # (If Required): ----------

Water Source: (Check One) Public [X] Well [ ] Well Tag # (If Applicable): _____
(Required)

[X] 5 Day Turnaround [ ] 3 Day Turnaround [ ] 2 Day Turnaround [ ] 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
21	HCRHS UCF21	Hall near 100 Basement	4/30/17	8:00 AM/PM	X					
22	S22	Trainer rm Cooler fill station		AM / PM						
23	Tm23	Trainer Room B		AM / PM						
24	F24	Hall near 157 gym High		AM / PM						
25	F25	Hall near 157 gym Low		AM / PM						
26	F26	Girls locker gym A High		AM / PM						
AS X 27	F27	Girls locker gym B Low	Void	Void AM / PM		Void.				
28	F28	Boys locker gym B Low		AM / PM						
29	F29	Boys locker gym A High		AM / PM						
30	F30	Cafe 172		AM / PM	↓					

Released by: Alex Salvador Signature: [signature] Date/Time: 4/30/17

Released by: _____ Signature: _____ Date/Time: _____

5/3/17

EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

453
~ For Lab Use Only ~

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: 170330, 84 State Route 31 City/State/Zip: flemington NJ 08822
(Required) (Required)

P.O. #: ---------- Sampled By: Alex Salvador License # (If Required): ----------

Water Source: (Check One) Public [X] Well [ ] Well Tag # (If Applicable): _____
(Required)

[X]	5 Day Turnaround	[ ]	3 Day Turnaround	[ ]	2 Day Turnaround	[ ]	1 Day Turnaround - Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	Temp at Time of Receipt:
31	HCRHS UCF31	9/10 Kitchen A	4/30/17	8:15 (AM)/PM	X					
32	IM32	9/10 Kitchen B		AM/PM						
33	S33	9/10 Kitchen C		AM/PM						
34	S34	9/10 Kitchen D		AM/PM						
35	S35	9/10 Kitchen E		AM/PM						
36	S36	9/10 Kitchen F		AM/PM						
37	S37	9/10 kitchen G		AM/PM						
38	H38	9/10 kitchen H		AM/PM						
39	S39	9/10 Kitchen I		AM/PM						
40	P40	Cafe' 174 F		AM/PM	↓					

Released by: Alex Salvador	Signature:	Date/Time:	
Released by:	Signature:	Date/Time:	5/3/17

EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

453
~ For Lab Use Only ~

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: 170330 / 84 State Route 31 City/State/Zip: Flemington NJ 08822
(Required) (Required)

P.O. #: ---------- Sampled By: License # (If Required): ----------

Water Source: (Check One) Public [X] Well [ ] Well Tag # (If Applicable):
(Required)

[X] 5 Day Turnaround [ ] 3 Day Turnaround [ ] 2 Day Turnaround [ ] 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
41	HCRHSUCF41	Cafe' 173 A	4/30/17	8:30 AM/PM	X					
42	S42	Cafe 173 E		AM / PM						
43	F43	Hall near 128		AM / PM						
44	F44	Hall near 137		AM / PM			NOT RECEIVED			
45	F45	Hall near 150		AM / PM						
46	S46	Kitchen 5		AM / PM						
47	S47	Sunroom		AM / PM						
8				AM / PM						
9				AM / PM						
10				AM / PM						

Released by: Alex Salvador Signature: Date/Time:

Released by: Signature: Date/Time:

5/3/17

Client Number: 201327 **Report Number:** 17-05-00447

Project/Test Address: 170330; 84 State Route 31; Flemington, NJ 08822

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
17-05-00447-014	HCRHSLC S14	04/30/2017	ROOM 657	1.43	05/05/2017	
17-05-00447-015	HCRHSLC F15	04/30/2017	HALL NEAR SS OFFICE	<1.00	05/05/2017	
17-05-00447-016	HCRHSLCI M16	04/30/2017	ROOM 702 B	<1.00	05/05/2017	
17-05-00447-017	HCRHSLC F17	04/30/2017	ROOM 702 C	<1.00	05/05/2017	
17-05-00447-018	HCRHSLC S18	04/30/2017	ROOM 714	<1.00	05/05/2017	
17-05-00447-019	HCRHSLC S19	04/30/2017	ROOM 716 A	<1.00	05/05/2017	
17-05-00447-020	HCRHSLC S20	04/30/2017	ROOM 716 B	<1.00	05/05/2017	
17-05-00447-021	HCRHSLC S21	04/30/2017	ROOM 716 C	<1.00	05/05/2017	
17-05-00447-022	HCRHSLC S22	04/30/2017	ROOM 716 D	<1.00	05/05/2017	
17-05-00447-023	HCRHSLC S23	04/30/2017	ROOM 716 E	<1.00	05/05/2017	
17-05-00447-024	HCRHSLC S24	04/30/2017	ROOM 716 F	<1.00	05/05/2017	
17-05-00447-025	HCRHSLC F25	04/30/2017	HALL NEAR 810 LOW	<1.00	05/05/2017	
17-05-00447-026	HCRHSLC F26	04/30/2017	HALL NEAR 810 HIGH	<1.00	05/05/2017	
17-05-00447-027	HCRHSLC F27	04/30/2017	HALL NEAR 821 LOW	<1.00	05/05/2017	
17-05-00447-028	HCRHSLC F28	04/30/2017	HALL NEAR 821 HIGH	<1.00	05/05/2017	
17-05-00447-029	HCRHSLC S29	04/30/2017	ROOM 825	<1.00	05/05/2017	
17-05-00447-030	HCRHSLC F30	04/30/2017	COMMONS KITCHEN SIDE LOW	<1.00	05/05/2017	
17-05-00447-031	HCRHSLC F31	04/30/2017	COMMONS KITCHEN SIDE	<1.00	05/05/2017	
17-05-00447-032	HCRHSLC S32	04/30/2017	11/12 KITCHEN A	1.94	05/05/2017	
17-05-00447-033	HCRHSLC S33	04/30/2017	11/12 KITCHEN B	26.6	05/05/2017	

Client Number: 201327 **Report Number:** 17-05-00447

Project/Test Address: 170330; 84 State Route 31; Flemington, NJ 08822

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
17-05-00447-034	HCRHSLCS34	04/30/2017	11/12 KITCHEN C	1.77	05/05/2017	
17-05-00447-035	HCRHSLCS35	04/30/2017	11/12 KITCHEN D	<1.00	05/05/2017	
17-05-00447-036	HCRHSLCS36	04/30/2017	11/12 KITCHEN E	4.51	05/05/2017	
17-05-00447-037	HCRHSLCS37	04/30/2017	11/12 KITCHEN F	11.9	05/05/2017	
17-05-00447-038	HCRHSLCH38	04/30/2017	11/12 KITCHEN G	2.66	05/05/2017	
17-05-00447-039	HCRHSLCS39	04/30/2017	11/12 KITCHEN H	<1.00	05/05/2017	
17-05-00447-040	HCRHSLCIM40	04/30/2017	11/12 KITCHEN I	<1.00	05/05/2017	
17-05-00447-041	HCRHSLCF41	04/30/2017	COMMONS NEAR SCHOOL STORE	<1.00	05/05/2017	
17-05-00447-042	HCRHSLCF42	04/30/2017	COMMONS NEAR SCHOOL STORE HIGH	1.19	05/05/2017	
17-05-00447-043	HCRHSLCF43	04/30/2017	FIELD HOUSE G LOCKER A	3.79	05/05/2017	
17-05-00447-044	HCRHSLCF44	04/30/2017	FIELD HOUSE G SIDE FOYER	<1.00	05/05/2017	
17-05-00447-045	HCRHSLCF45	04/30/2017	WRESTLING ROOM	<1.00	05/05/2017	
17-05-00447-046	HCRHSLCF46	04/30/2017	FIELD HOUSE B SIDE FOYER	<1.00	05/05/2017	
17-05-00447-047	HCRHSLCF47	04/30/2017	FIELD HOUSE B LOCKER A	1.74	05/05/2017	
17-05-00447-048	HCRHSLCF48	04/30/2017	ROOM 900 PREP	3.08	05/05/2017	
17-05-00447-049	HCRHSLCF49	04/30/2017	ROOM 904 PREP	5.02	05/05/2017	
17-05-00447-050	HCRHSLCF50	04/30/2017	HALL NEAR 910 LOW	<1.00	05/05/2017	
17-05-00447-051	HCRHSLCF51	04/30/2017	HALL NEAR 910 HIGH	<1.00	05/05/2017	
17-05-00447-052	HCRHSLCS52	04/30/2017	ROOM 914 PREP	4.12	05/05/2017	
17-05-00447-053	HCRHSLCF53	04/30/2017	HALL NEAR 919 LOW	<1.00	05/05/2017	

Environmental Hazards Services, L.L.C

Client Number: 201327 **Report Number:** 17-05-00447

Project/Test Address: 170330; 84 State Route 31; Flemington, NJ 08822

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
17-05-00447-054	HCRHSLC F54	04/30/2017	HALL NEAR 919 HIGH	<1.00	05/05/2017	
17-05-00447-055	HCRHSLC S55	04/30/2017	ROOM 923 PREP	<1.00	05/05/2017	
17-05-00447-056	HCRHSLC S56	04/30/2017	11/12 KITCHEN J	<1.00	05/05/2017	
17-05-00447-057	HCRHSLC S57	04/30/2017	11/12 KITCHEN K	<1.00	05/05/2017	
17-05-00447-058	HCRHSLC F58	04/30/2017	11/12 LEFT COMMONS	<1.00	05/05/2017	
17-05-00447-059	HCRHSLC F59	04/30/2017	11/12 RIGHT COMMONS	<1.00	05/05/2017	

Method: SM 3113B-2010

Accreditation #: NJ VA008

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

17-05-00447

Due Date:
05/10/2017
(Wednesday)
AE

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: 170330, 84 State Route 31 City/State/Zip: Flemington NJ 08822
(Required)

P.O. #: ---------- Sampled By: Alex Salvador License # (If Required): ----------

Water Source: (Check One) Public [X] Well [ ] Well Tag # (If Applicable): _____
(Required)

[X] 5 Day Turnaround [ ] 3 Day Turnaround [ ] 2 Day Turnaround [ ] 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
1	LCHCRHSLCF1	Hall near 406 G	4/30/17	8:30 AM / PM	X					
2	F2	Hall near 406 B		AM / PM						
3	F3	Work Room		AM / PM						
4	F4	Room 500		AM / PM						
5	F5	Hall near 504 Door		AM / PM						
6	F6	Hall near 504		AM / PM						
7	F7	Hall near 518 Low		AM / PM						
8	F8	Hall near 518 High		AM / PM						
9	F9	Hall near 612		AM / PM						
10	F10	Hall near 646		AM / PM						

Released by: Alex Salvador	Signature:	Date/Time: 4/30/17
Released by:	Signature:	Date/Time:

5/3/17

EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

447
~ For Lab Use Only ~

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: 170330, 84 State Route 31 City/State/Zip: Flemington NJ 08822
(Required) (Required)

P.O. #: ---------- Sampled By: Alex Salvador License # (If Required): ----------

Water Source: (Check One) Public [X] Well [ ] Well Tag # (If Applicable): _____
(Required)

[X] 5 Day Turnaround [ ] 3 Day Turnaround [ ] 2 Day Turnaround [ ] 1 Day Turnaround - Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
11	LCHCRHSLC511	Room 650	4/30/17	8:45 AM/PM	X					
12	F12	Hall near 652		AM/PM						
13	F13	Room 657		AM/PM						
14	S14	Room 657		AM/PM						
15	F15	Hall near SS office		AM/PM						
16	IM16	Room 702 B		AM/PM						
17	F17	Room 702 C		AM/PM						
18	S18	Room 714		AM/PM						
19	S19	Room 716 A		AM/PM						
20	S20	Room 716 B		AM/PM	↓					

Released by: Alex Salvador	Signature:	Date/Time: 4/30/17
Released by:	Signature:	Date/Time:

5/3/17

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

447
~ For Lab Use Only ~

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: 170330 , 84 state Route 31 City/State/Zip: Flemington NJ 08822
(Required) (Required)

P.O. #: ---------- Sampled By: Alex Sawadar License # (If Required): ----------

Water Source: (Check One) Public [X] Well [ ] Well Tag # (If Applicable): _____
(Required)

[X] 5 Day Turnaround [ ] 3 Day Turnaround [ ] 2 Day Turnaround [ ] 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
21 LC	HCRHS LC S21	Room 716 C	4/30/17	9:00 (AM) / PM	X					
22	S22	" " D		AM / PM						
23	S23	" " E		AM / PM						
24	S24	" " F		AM / PM						
25	F25	Hall near 810 Low		AM / PM						
26	F26	Hall near 810 High		AM / PM						
27	F27	Hall near 821 Low		AM / PM						
28	F28	Hall near 821 High		AM / PM						
29	S29	Room 825		AM / PM						
30 (10)	F30	Commons Kitchen side low		AM / PM	↓					

Released by: Alex Sawadar	Signature:	Date/Time:	
Released by:	Signature:	Date/Time:	

5/3/17

EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

447
~ For Lab Use Only ~

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: 170330, 84 State Route 31 City/State/Zip: Flemington NJ 08822
(Required) (Required)

P.O. #: ---------- Sampled By: Alex Salvador License # (If Required): ----------

Water Source: (Check One) Public [X] Well [ ] Well Tag # (If Applicable): _____
(Required)

[X] 5 Day Turnaround	[ ] 3 Day Turnaround	[ ] 2 Day Turnaround	[ ] 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
31LC	HCRHS LC F31	Commons Kitchen Side	4/30/17	9:15 AM/PM	X					
32	S32	11/12 Kitchen A	"	" AM/PM						
33	S33	" " B	"	" AM/PM						
34	S34	" " C	"	" AM/PM						
35	S35	" " D	"	" AM/PM						
36	S36	" " E	"	" AM/PM						
37	S37	" " F	"	" AM/PM						
38	H38	" " G	"	" AM/PM						
39	S39	" " H	"	" AM/PM						
40	im 40	" " I	"	" AM/PM						

Released by: Alex Salvador	Signature:	Date/Time: 4/30/17
Released by:	Signature:	Date/Time:

5/3/17

EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

447
~ For Lab Use Only ~

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: 170330, 84 State Route 31 City/State/Zip: Flemington NJ 08822
(Required) (Required)

P.O. #: ---------- Sampled By: Alex Salvador License # (If Required): ----------

Water Source: (Check One) Public [X] Well [ ] Well Tag # (If Applicable): _____
(Required)

X	5 Day Turnaround		3 Day Turnaround		2 Day Turnaround		1 Day Turnaround* Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
41	LC HCRHS LC F41	Commons near School Store	4/30/17	9:30 AM / PM	X					
42	F42	Common near school/Store High		AM / PM						
43	F43	Field House G locker A		AM / PM						
44	F44	Field House G side Foyer		AM / PM						
45	F45	wrestling Room		AM / PM						
46	F46	Field House B side foyer		AM / PM						
47	F47	Field House B locker A		AM / PM						
48	F48	Room 900 prep		AM / PM						
49	F49	Room 904 prep		AM / PM						
50	F50	Hall near 910 Low		AM / PM	↓					

Released by: Alex Salvador	Signature:	Date/Time: 4/30/17	
Released by:	Signature:	Date/Time:	

5/3/17

EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

447
~ For Lab Use Only ~

Company Name: LEW Corporation Account #: 201327

Address: 1090 Bristol Road City/State/Zip: Mountainside, NJ 07092

Phone: 908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: 170330 / 84 state Route 31 City/State/Zip: (Required) Flemington NJ 08822

P.O. #: ---------- Sampled By: Alex Salvador License # (If Required): ----------

Water Source: (Check One) (Required) Public [X] Well [ ] Well Tag # (If Applicable): _____

[X] 5 Day Turnaround	[ ] 3 Day Turnaround	[ ] 2 Day Turnaround	[ ] 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals: Lead	Metals: Copper	Metals: Other	Field Parameters: Field pH at time of Collection:	Field Parameters: Temp. at time of Collection:	LAB USE: Temp at Time of Receipt:
51	LC HCRHS LC F51	Hall near 910 High	4/30/17	10:02 AM/PM	X					
52	S52	Room 914 prep		AM/PM						
53	F53	Hall near 919 low		AM/PM						
54	F54	Hall near 919 High		AM/PM						
55	S55	Room 923 prep.		AM/PM						
56	S56	11/12 Kitchen J		AM/PM						
57	S57	11/12 Kitchen K		AM/PM						
58	F58	11/12 left Commons		AM/PM						
59	F59	11/12 Righ Commons.		AM/PM						
10				AM/PM						

Released by: Alex Salvador	Signature:	Date/Time: 4/30/17
Released by:	Signature:	Date/Time:

5/3/17